

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

October 19, 2006

Stacie Kaes, Administrator Magic Valley Manor Assisted Living PO Box 306 Wendell, ID 83355

License #: RC-671

Dear Ms. Kaes:

On September 8, 2006, a survey was conducted at Magic Valley Manor - Assisted Living. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Chris Laumann, Health Facility Surveyor, Residential Community Care Program, at (208) 334-6626.

Sincerely,

CHRIS LAUMANN

Team Leader

Health Facility Surveyor

Residential Community Care Program

CL/slc

c:

Jamie Simpson, MBA, QMRP Supervisor, Residential Community Care Program



JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

September 14, 2006

Stacie Kaes, Administrator Magic Valley Manor - Assisted Living PO Box 306 Wendell, ID 83355 FILE COPY

Dear Ms. Kaes:

On September 8, 2006, a life safety code survey was conducted at Magic Valley Manor - Assisted Living. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by October 8, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED **IDENTIFICATION NUMBER:** A. BUILDING 01 - ENTIRE BUILDING B. WING 13R671 09/08/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER **210 N IDAHO MAGIC VALLEY MANOR - ASSISTED LIVING** WENDELL, ID 83355 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (EACH DEFICIENCY MUST BE PRECEEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE COMPLETE DATE PRÉFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety standards of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on Sept 8, 2006. The surveyors conducting the survey were: Eric Mundell Team Leader Health Facility Surveyor Chris Laumann Fire/ Life Safety Surveyor

Bureau of Facility Standards

TITLE

(X6) DATE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888 ASSISTED LIVING Non-Core Issues Punch List

						λ
Facility Name		Physical Address			Phone Number	
Magic Valley Mana		210 N	ldaho		(208) S36	0-6623
Administrator		City			ZIP Code	
Kathy Adams Survey TeamLeader		Wendell Survey Type			833S <i>S</i>	•
Survey Team-Leader					Survey Date	
Chris Laur	200	Fire/	Life Safer		& Sept	2006
NON-CORE ISSUES				J		
ITEM RULE#			DESCRIPTION			DATE RESOLVED
1 16.03.23,405.02	Fire alarm					
	Fire alarm Smoke	detection	n Siskm m	contenance. A	Louant	9/22/66
	fre alarm con	ification	documente	tion could no	ot be	
	Paduced.					
2. 16.03.22.405.02.	16.03.20.405.00. Fire alarm flow alarm. Annual certification documents					
	not activate when flow test was conducted. Alarm					9/22/06
						\
· · ·	is not activating when water flows through the					
	sprinkler system		,			
3. 16,03,22,402,	Fire and Life so	in the second	setromenuos:	Stira foam t	Darrier wa	\$ 9/8/06
	found being use	das e	deflector A	Hached to	an HVAC	! /
	vent duct. Rea	- exit a	ias found a	s not provi	de ans	, , , , , , , , , , , , , , , , , , , ,
	illumination o	f Mead	is of earns	to the ex	terror	9/22/06
	landing.		J			
***************************************					RECEIVE	Ý
					OCT 1.0 2006	
Response Required Date	Signature of Fadility Representative	1_1		FAI	~ 2000	
800 +200b	Math.	1 Koth	Inne	" 71(CILITY STANDARDS	2